



MINISTRY OF HEALTH
DEPARTMENT OF PUBLIC HEALTH AND SANITATION

REPORT FOR CERTIFICATION OF OCCUPANCY OF OPM SAFE HOUSE
PROJECT 2

23/4/2021

TO CULTURE INFORMATION AND PASTORALIST DEVELOPMENT
SOLOLO

RE – INSPECTION REPORT ON HOUSES FOR CERTIFICATION OF OCCUPANCY

INTRODUCTION

Public health office has the responsibility to inspect and satisfy the habitability of structures intended for human occupation and certify suitability.

The inspection was carried out on request by CIPAD. The houses were built in different sub location hence this report will be a representative of all the 8 houses visited and inspected. The houses are 2 roomed, sloppy roofs and semi-permanent constructed using tree poles, mudded and plastered with cement mortar. The house measures 5M width X 8M length portioned at 5M X 4M rooms.

The house visited and inspected are tabulated below

No	Beneficiary names	Family No	locations
1	Qabale Huqa	122	Sololo Ramata
2	Malicha Tarata	014	Madoadi
3	Daki Bonaya	048	Wayegoda
4	Malicha Bonaya	077	Damballafachana
5	Sake Godana	105	Sololo Makutano
6	Fatuma Kadu	076	Sololo Makutano
7	Rufo Guracha	078	Golole
8	Antuta Ali	051	Golole

1. CONDITIONS AND DEFECTS

- The external walls have rough plastered with cement mortar
- The internal walls were smooth finished with cement plaster and whitewash applied
- The roof have iron sheets , no evidence of leaking was observed
- The wall is approximately 2.5 m high

- The floors was newly constructed and finished with cement screed
- There was skirting running along the foundation walls to protect from dampness and water seepage

2. VENTILATION AND LIGHTING

- There was 1 metallic door provided for each house and well hinged to the door frames and the wall structures
- There was no internal door fitted
- The houses have 2 metallic windows measuring 50CM X 70CM. The windows were 1 per room ,there was adequate ventilation in the rooms
- There was adequate natural light through the windows and door during the day

3. FURNISHES AND BEDDINGS

- The house were poorly furnished , most has had 2-3 plastic chairs
- There were 2 single metallic beds measuring 3ft X6ft
- There were 2 medium size 3ft X 6ft mattresses
- There were 2 – 6 Blankets seen

4. SANITARY FACILITIES

- Each house was provided with 1 pit latrine, the superstructure was constructed with iron sheets. The floor was cemented, ventilation pipe was provided to remove foul air.
The compound was fenced with euphorbia as a live fence but has many spaces does not provide adequate protection.
The compound was littered with plastic bottles and papers.

5. RECOMMENDATION

1. The poles and timber can be attacked by the termites in future application of anti-termites chemicals or old oil engines around the foundation and exposed parts of timbers and poles
2. The family to clean the compound of plastic materials and clear the over grown grasses

6. CONCLUSION

The houses provides the minimum standard for occupation of safety and health, therefore the public health office hereby approves that all the 8 houses satisfies the requirements of public health Act and the building regulations there under. The public health office has no objection for the occupancy of the houses.

Thank you


RACHAEL T. GABABA
SUB COUNTY PUBLIC HEALTH OFFICER
MOYALE SUB COUNTY



